

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2018

Submitted Date:

09/10/2018

Document Number:

688800285

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
326612 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 13 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258940	WELL	PR	01/09/2001	GW	067-08394	MONTGOMERY FEDERAL 2	EI

General Comment:

On September 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Montgomery Federal #2. For the most recent field inspection report of this facility, please refer to document #674900547.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Label and placard directly on tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near location entrance. Old sign remains on location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Concrete pad and surrounding gravel is wet and stained.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 10/10/2018
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel enclosure.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Stock panel enclosure.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel enclosure around separator, meter run, and telemetry equipment.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.267798,-107.644490
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	21 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 258940 Type: WELL API Number: 067-08394 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On September 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Montgomery Federal #2. For the most recent field inspection report of this facility, please refer to document #674900547. The pump jack is leaking oil onto the concrete pad and the surrounding gravel.	hughesj	09/10/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800286	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4574581