

# Inspection Photos

Operator: BP Production

API: 05-067-07487

Date: 9/13/2018



**Photo 1. View of the project area from the southeastern corner facing center.**





**Photo 2. View of the eastern project area from the southeastern corner facing northward.**





**Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is largely comprised of grasses such as crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).**





**Photo 4. View of the western project area from the southwestern edge facing northward. Vegetation in the foreground is dry and mostly comprised of annual weeds such as tumblemustard (*Sysimbrium* sp.)**





Photo 5. View of Canada thistles (*Cirsium arvense*) in southwestern drainage.





**Photo 6. View of area along the access road where culvert is blocked on upstream side and stormwater flows over the road surface resulting in erosion on the road and where it flows into the drainage.**





**Photo 7. View of Russian thistles (*Salsola tragus*) on the well pad growing up to 3 feet tall. These will break off and become debris.**





**Photo 8. View Russian thistle debris that has blown off of the project area, east of the well pad.**