

GV 33-22 Frac Pad
API# 05-045-06730
Inspection# 689701812



Location photo.



GV 33-22 Frac Pad
API# 05-045-06730
Inspection# 689701812



Dead weed debris. Inadequate containment for tank.

GV 33-22 Frac Pad
API# 05-045-06730
Inspection# 689701812



Dead weed debris. Inadequate containment for tank.

GV 33-22 Frac Pad
API# 05-045-06730
Inspection# 689701812



Dead weed debris. Inadequate containment for tank.

GV 33-22 Frac Pad
API# 05-045-06730
Inspection# 689701812



Road damage at entrance of location.

GV 33-22 Frac Pad
API# 05-045-06730
Inspection# 689701812



Road damage at entrance of location.