

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/22/2018

Submitted Date:

10/23/2018

Document Number:

680403959**FIELD INSPECTION FORM**Loc ID 316810 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 600 TRAVIS STREET SUITE 300City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Miller, Mandy	970-739-3786	mandym@paradoxresources.com	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232871	WELL	SI	03/29/2018	GW	113-06060	COCKLEBUR DRAW UNIT 3	SI

**General Comment:**Bradenhead test performed 10/22/2018

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	Potholes and washed area noted on inspection doc#680402083 repaired. CA completed		
Corrective ActionL		Date:	
Type	Access		
comment:	BLM		
Corrective ActionL		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign at edge of location.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	CA for scrap pipe completed via FIRR Doc#401176818 on 1/3/2017.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe barricade around wellhead.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	#		
Comment:	Off location flowline to production facilities ~.5 mi. NW.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	232871	Type:	WELL	API Number:	113-06060	Status:	SI	Insp. Status:	SI
BradenHead									
Comment:	<p>Bradenhead test perfomed 10/22/2018. Tbg pressure 1920 psi, casing pressure 1900, bradenhead pressure &lt;5 psi. Bradenhead pressure down to 0 after 5 minutes. No change in tubing or casing pressure.</p> <p>Well shut in 12/2015. No current MIT on record or delinquent as required by Rule 326 as noted on inspection doc#680402083.</p> <p>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</p>								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: [Location covered in vegetation.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680403965	Inspection photos 10/22/2018	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4618877">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4618877</a>