

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank lacks NFPA placard. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/16/2019
Type	WELLHEAD		
Comment:	Incorrect producer information on wellhead sign. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	01/16/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds have grown around tank battery and location. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/16/2019
Type	TRASH		
Comment:	Barbed wire rolls and miscellaneous pipe fittings inside of tank berm, barbed wire rolls are stored on production tank landing, miscellaneous trash around tank berm. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/16/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock fencing		

Corrective Action:	Date:
Equipment:	
Type: Plunger Lift # 1	corrective date
Comment:	
Corrective Action:	Date:
Type: Horizontal Heated Separator # 1	
Comment:	
Corrective Action:	Date:
Type: Gas Meter Run # 1	
Comment:	
Corrective Action:	Date:
Type: Bird Protectors # 1	
Comment:	
Corrective Action:	Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216955 Type: WELL API Number: 069-06142 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674301047	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647251