

# Inspection Photos

Operator: Catamount Energy

API: 05-007-06220

Date: 11/06/2018



**Photo 1. View of the western project area from southwestern corner facing northward.**



**Photo 2. View of erosional channel approximately 1.5 feet wide and deep within the western project area.**



**Photo 3. View of the northern project area from the northwestern corner facing eastward.**



Photo 4. View of the eastern project area from the northeastern corner facing southward. Drilling equipment remains on location. Rilling is occurring in several areas along the cut-slope. Poor vegetative cover here. Some desirable species such as Indian ricegrass (*Achnatherum hymenoides*) and western wheatgrass (*Pascopyrum smithii*) observed. However bare ground and weeds such as Russian thistle (*Salsola tragus*) dominate.



**Photo 5. View of the southeastern cut-slope. Poor revegetation and rilling is occurring throughout.**