

Inspection Photo (s)
Shideler 19-9B1
API # 05-045-07968
Inspection # 689302587



Location Photo #1



Location Photo #2, containment wall damage.

Inspection Photo (s)
Shideler 19-9B1
API # 05-045-07968
Inspection # 689302587



Location Photo #3, Support bracket broken.

Location Photo #4, Support bracket broken.