

Inspection Photos

Operator: Hilcorp Energy

API: 05-067-09460

Date: 12/19/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View the eastern project area from the northeastern corner facing southward. Revegetation is progressing in areas, but weedy with annual weeds in other areas.



Photo 3. View of jointed goatgrass (*Acroptilon repens*) within the northwestern project area. Also present within the northeastern project area.



Photo 4. View of the western project area from the northwestern corner facing southward.