

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08834



Tank heater being repaired during this inspection.



Damaged 1" high pressure hose where release occurred.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08834



Fitting that failed hose was attached to in center of photo.



Skid mounted compressor with containment area full of ice.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08834



Flow path from compressor skid.



Produced water puddled up in SW corner of location.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08834



Earthen berm observed during this inspection. Reportedly stopped flow from exiting location.



Down gradient of previous photo.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08834



Photo of release flow path from SW corner of location.



Roy Annala A #2 tank battery.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08834



Close up photo along flow path of release.



Frozen puddle of alleged E and P waste.