

Inspection Photos

1/31/2019

Operator: BISON OIL & GAS II LLC - 10661

Location ID: 425364

Inspection Doc. Number: 682504459

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC




Photo 1: 2013 Google earth aerial imagery. A disturbance area of 4.98 acres was measured using a Trimble Juno 3B handheld device

Inspection Photos
Operator: BISON OIL & GAS II LLC - 10661
Location ID: 425364



Photo 2: Photo taken from the north end of the location, facing east. Photos 2- 5 provide an overview of the location from east, southeast, southwest, to west.

Inspection Photos
Operator: BISON OIL & GAS II LLC - 10661
Location ID: 425364



Photo 3: See comments under photo 2.

Inspection Photos
Operator: BISON OIL & GAS II LLC - 10661
Location ID: 425364



Photo 4: See comments under photo 2.



Photo 5: See comments under photo 2.



Photo 6: Photo taken from the location entrance. Photo shows sign with incorrect operator information.

Inspection Photos
Operator: BISON OIL & GAS II LLC - 10661
Location ID: 425364



Photo 7: Photo taken from the tank battery. Photo shows sign with incorrect operator information.

Inspection Photos
Operator: BISON OIL & GAS II LLC - 10661
Location ID: 425364



Photo 8: Photo taken from the northeast corner of the location, facing west. Photo shows current interim areas and the location.



Photo 9: Photo of culvert at access road. Culvert appears to be in proper functioning condition.

Inspection Photos
Operator: BISON OIL & GAS II LLC - 10661
Location ID: 425364



Photo 10: Photo taken from the southeast corner of the location, facing north. Photo shows current interim areas and the location.

Inspection Photos
Operator: BISON OIL & GAS II LLC - 10661
Location ID: 425364



Photo 11: Photo taken from the southeast corner of the location, facing west. Photo shows current interim areas and the location.



Photo 12: Photo taken from the west end of the location. Photo shows wildlife appears to have burrowed into the stormwater berm. Maintenance required.



Photo 13: Photo taken from the west end of the location. Photo shows wildlife appears to have burrowed into the stormwater berm. Maintenance required.