

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2019

Submitted Date:

02/15/2019

Document Number:

678302396

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Contact Information:

Contact Name	Phone	Email	Comment
Hamlin, Phil		Phil.Hamlin@anadarko.com	
, Anadarko		COGCCinspections@Anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445916	SPILL OR RELEASE	CL	10/10/2016		-	SPILL/RELEASE POINT	EI

General Comment:

[inspection related to complaint filed by landowner Mr. Martindale regarding status of ongoing remediation project 9871.](#)

Location

Overall Good:

Emergency Contact Number:

Comment: no ongoing oil and gas production equipment at site where tank battery had previously been located so no signs present or required

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: spill 445916 closed with initiation of approved site investigation and remediation plan (project 9871).

Last annual summary of monitoring and remediation activities received in May 2018 with COA to approved supplemental form 27 requiring annual reporting of progress.
 Approval of activities by operator included installation of additional monitoring wells as POC towards north had not been achieved. Inspection indicates the presence of at least 16 MW where 14 were in place at time of previous annual report in 2018.
 Attached photo shows monitoring wells at site of remediation project 9871

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 445916 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678302397	Monitoring wells	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735902