

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2019

Submitted Date:

02/18/2019

Document Number:

682600629**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Kosola, Jason _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 51065Name of Operator: LOEB LLC* HERMAN LAddress: P O BOX 838City: LAWRENCEVILLE State: IL Zip: 62439**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Middagh, Jesse	815-556-0756	jesse@loeboil.com	
Mattox, Jennifer	303-692-3144	jennifer.mattox@state.co.us	Oil and Gas Inspections and Compliance
Pelton, Shane	620-617-5870	shane@loeboil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
462031	TANK BATTERY	AC	02/14/2019		-	White AG Tank Battery	EI

General Comment:

Gas observed to be venting from open pipe on both crude oil tanks on location. Referred to Colorado Department of Health and Environment.

Rabbit burrows in walls of containment berm compromising secondary containment.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Truck Loadout	<= 1 bbl		
Comment: Stained soil inside containment.				
Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.				Date: 03/20/2019

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Rabbit burrow in tank battery containment wall. Inadequate berms around tank(s)				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).				Date: 03/20/2019

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>



Inspected FacilitiesFacility ID: 462031 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401942867	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737404
682600638	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737397