

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2019

Submitted Date:

03/16/2019

Document Number:

696100518

FIELD INSPECTION FORM

Loc ID 330416 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251289	WELL	PR	07/01/2018	OW	123-19092	HSR-KNOX 12-3	SI

General Comment:

This is a WELL Inspection.
Well is SI.
Battery & ALL equipment is Shut-down.
Centralized Battery serves 2 Location IDs (330417, 330416).
Refer to FIR #696100516 and/or Location ID #330417 for Battery / Facility, Equipment info.

Weather/Conditions: Clear / Patches of snow & mud.
No Corrective Actions identified.

Location						
Lease Road:						
	Type	Access				
	comment:	Adequate				
	Corrective Action	L			Date:	
Overall Good: <input type="checkbox"/>						
Signs/Marker:						
	Type	WELLHEAD				
	Comment:					
	Corrective Action:				Date:	
Emergency Contact Number:						
	Comment:					
	Corrective Action:				Date:	_____
Overall Good: <input type="checkbox"/>						
Spills:						
Type	Area	Volume				
In Containment: No						
	Comment:					
<input type="checkbox"/> Multiple Spills and Releases?						
Fencing/:						
	Type	WELLHEAD				
	Comment:	Iron panel				
	Corrective Action:				Date:	
	Type	OTHER				
	Comment:	Refer to FIR #696100516 and/or Location ID #330417 for additional Fencing info.				
	Corrective Action:				Date:	
Equipment:						
Type:		#			corrective date	
	Comment:	Refer to FIR #696100516 and/or Location ID #330417 for additional Equipment info.				
	Corrective Action:				Date:	
Type:	Plunger Lift	#	1			
	Comment:					
	Corrective Action:				Date:	
Type:	Other	#	1			
	Comment:	Bradenhead appears plumbed to surface.				
	Corrective Action:				Date:	
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.423572,-104.885159	

Comment:	Centralized Battery serves 2 Location IDs (330417, 330416). Refer to FIR #696100516 and/or Location ID #330417 for Tanks & Berms info.			
Corrective Action:				Date:
Paint				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 251289 Type: WELL API Number: 123-19092 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Observed SI. Production valves shut.
COGCC records indicate Last prod: 01/2019.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100519	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765228