

# Inspection Photos

Operator: Enervest Operating  
Location/API #: 067-07306  
Date: 4-9-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward.





Photo 3. View of the southern project area from the southwestern corner facing eastward.





Photo 4. View of area along access road where it appears stormwater flows recently crossed over the road (facing upstream), indicating that culvert is not adequately sized/designed.





Photo 5. View of area downstream from Photo 4, where stormwater flows recently crossed over the road, depositing sediment from the road.





Photos 6-9. View of wire debris and waste within the interim reclamation area.