

Inspection Photos

Operator: Catamount Energy
Location/API #: 067-05464
Date: 4-17-2019



Photo 1. View of wattles in the eastern project area that are full of sediment.



Photo 2. View of eastern diversion ditch that is full of sediment and eroding. Additional stabilization is needed here.



Photo 4. View of wattle in the northern project area that is full of sediment.



Photo 5. View of wattle in the northern project area that is not functioning.



Photo 6. View of cobble run-down within the western project area that needs maintenance due to sediment accumulation.