



00790862

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. <b>Colo. 03130-8</b>	
2. NAME OF OPERATOR <b>Willis C. Walker</b>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR <b>P. O. Box 681, Walden, Colorado</b>		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <b>660' S. N &amp; 1980' E/W lines Sec. 21 (NE/4 NW/4) 9N-78W</b>		8. FARM OR LEASE NAME <b>Engler Grist Henge</b>	
14. PERMIT NO.		9. WELL NO. <b>1</b>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>8224' KB</b>		10. FIELD AND POOL, OR WILDCAT <b>So. McCallum</b>	
12. COUNTY OR PARISH <b>Jackson</b>		13. STATE <b>Colorado</b>	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 21-9N-78W</b>			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>		
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Plug and Abandon Well as follows:

1. Place cement plug across perms from 5600 to 5870'.
2. Place 50' cement inside casing and 50' above casing.
3. Fill hole with mud.
4. Place 10 sack cement plug at top of surface pipe and erect proper marker.
5. 100' at base of surface casing, 50' in and 50' out.
6. Clean and level location.

DVR	
FJP	✓
HHM	✓
JAM	✓
JJD	✓

BEST IMAGE  
AVAILABLE

RECEIVED

FEB 11 1969

COLO. OIL & GAS CONS. COMM.

18. I hereby certify that the foregoing is true and correct

SIGNED Willis C. Walker TITLE Lessee DATE 8-30-67

(This space for Federal or State office use)

APPROVED BY RUDOLPH C. BAUER, JR. TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**APPROVED**

SEP 3 1967

RUDOLPH C. BAUER, JR.  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side