

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402018938

Date Received:

04/24/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>	<u>(505)324-5188</u>	<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900088

Inspection Date: 03/18/2019

FIR Submit Date: 03/19/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326687

Location Name: PENROSE-N32N6W Number: 8SWSW County: LA PLATA

Qtrqr: SWS Sec: 8 Twp: 32N Range: 6W Meridian: N  
W

Latitude: 37.027520 Longitude: -107.529450

FACILITY - API Number: 05-067- -00 Facility ID: 262950

Facility Name: PENROSE Number: 1R

Qtrqr: SWS Sec: 8 Twp: 32N Range: 6W Meridian: N  
W

Latitude: 37.027520 Longitude: -107.529450

CORRECTIVE ACTIIONS:

1 CA# 123342

Corrective Action: Mark or remove guy line anchors.

Date: 04/19/2019

Response: CA COMPLETED

Date of Completion: 04/23/2019

Operator Comment: Marked guy line anchors. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 123343

Corrective Action: Stormwater controls need to be installed to stabilize erosion on eastern slopes and within erosional channels. Area along the flowline where sediment from this well pad and the adjacent well pad is deposited, needs to be revegetated. Stormwater flows entering this area need to be de-energized to prevent further sedimentation and allow for vegetation establishment.

Date: 04/19/2019

Response: CA COMPLETED

Date of Completion: 04/23/2019

Operator  
Comment: Stormwater controls were installed. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 4/24/2019 6:10:20 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402018939	Penrose 1R Resolution Photos
-----------	------------------------------

Total Attach: 1 Files