

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2019

Submitted Date:

04/19/2019

Document Number:

687904623

FIELD INSPECTION FORM

Loc ID 326067 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215812	WELL	PR	03/16/1990	GW	067-07417	MW JOHNSON A 1	PR

General Comment:

[Inspection of location with photos at the end of this inspection report.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Posted sign at entrance to location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on sign at entrance.		Date: _____
Corrective Action:			
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Cattle panels around produced water tank.		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed wire fence around location.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panels around separator.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment # 1			corrective date
Comment:	Wellhead with PVC bradenhead access.		
Corrective Action:			Date:
Type: Gas Meter Run # 1			
Comment:			
Corrective Action:			Date:
Type: Flow Line # 5			
Comment:	1-3" steel flowline from wellhead to separator. 1-2" steel flowline from wellhead blowdown to produced water tank. 1-2" steel flowline from separator dump valve to produced water tank. 1-1" steel flowline from separator to pump jack engine fuel gas. 1-3" steel flowline from separator to offsite dogleg.		
Corrective Action:			Date:

Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:	On separator stack and produced water tank vent.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Pump jack engine muffler actively releasing lube oil (Mixed with E&P waste) Oily gavel sourrounding muffler and adjacent area. Reoccurrence of this corrective action has taken place according to document# 685200425.		
Corrective Action:	Stop release immediately. Take necessary steps in engine repair or muffler reconfiguration and comply Rules 906 and 907		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 215812 Type: WELL API Number: 067-07417 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Fail	
Compaction	Pass	Compaction	Pass			
Ditches	Pass					

Comment: Spill prevention for engine exhaust tank is full and overflowing and needs emptied to prevent spill. oily and stained gravel around muffler and adjacent areas on East side of skid and below day tank.

Corrective Action: Remove impacted material per Rules 907 and 1002.f., self inspect/take measures to prevent future breakdown of BMPs

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402015544	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4801472
687904624	Oily gravel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4801467
687904625	Spill prevention full	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4801468
687904626	Spill prevention full	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4801469
687904627	standing liquid on ground	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4801470
687904628	Oily gravel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4801471