

Inspection Photos

Operator: Enduring Resources
Location/API #: 067-07636
Date: 4-22-2019



Photo 1. View of the northern project area from the northwestern corner facing eastward.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of erosion, sedimentation, and insufficient stormwater controls along the access road.