

Inspection Photos

Operator: Enduring Resources
Location/API #: 067-08647
Date: 4-22-2019



Photo 1. View of the eastern fill slope from the southeastern edge facing northward.



Photo 2. View of silt trap in the eastern project area that is full of sediment.



Photo 3. View of erosional scouring in the southern project area where concentrated stormwater flows off of the well pad.



Photo 4. View of the northwestern cut-slope that is not properly stabilized.