

Inspection Photos  
Location Name: Parker #44-15  
Location ID: 332886



Photo 1 WH



Photo 2 TNK BTRY

**Inspection Photos**  
**Location Name: Parker #44-15**  
**Location ID: 332886**



**Photo 3 Stained soil around produced water tank**



**Photo 4 Ground saturated from what appears to a leak at bottom of produced water tank. Mechanical issue: leak on tank.**

**Inspection Photos**  
**Location Name: Parker #44-15**  
**Location ID: 332886**



**Photo 5 Stained soil around produced water tank**



**Photo 6 Ground saturated from what appears to a leak at bottom of produced water tank.**

**Inspection Photos**  
**Location Name: Parker #44-15**  
**Location ID: 332886**



**Photo 7 Gage hatch open**

**Photo 8 Affected area soil approx. 8 feet long**

**Inspection Photos**  
**Location Name: Parker #44-15**  
**Location ID: 332886**



**Photo 9 Affected area approx. 5ft wide.**

**Photo 10 Dug down approx. 12 in ground still saturated.**