

Inspection Photos

API: 05-055-06165

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/1/2019

Inspection Photos



Photo 1. Facing southwest toward the access road.

Inspection Photos



Photo 2. There is a soil pile near the location along the access road. This area around the soil pile does not have adequate vegetation cover.

Inspection Photos



Photo 3. Facing back toward the northeast. The greyish area toward the soil pile is undesirable weeds (Kochia).

Inspection Photos



Photo 4. Weeds shown in previous photo 3 are beginning to germinate.

Inspection Photos



Photo 5. There are a few List B noxious weeds (Diffuse knapweed) in the area near the soil pile.

Inspection Photos



Photo 6. Facing southwest toward the location. Vegetation appears to be fully established.

Inspection Photos



Photo 7. Facing northeast toward the location. Vegetation appears to be fully established.

Inspection Photos



Photo 8. Facing northwest toward the location. Vegetation appears to be fully established.