



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	06/02/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 243122 Type: WELL API Number: 123-10913 Status: TA Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday May 2, 2019 at approximately 1347hrs, I Randy Silver                      Conducted an on-site inspection at a Kerr McGee site, Carl R Deepe #2, at                      API# 05-123-10913 in Weld County Colorado.                      While there, I observed a Well site that has been P&amp;A.                      During my inspection, the following possible compliance issues were observed:                      Unused equipment: Rule 603 f Corrective action date of 6-2-19                      Well has been P&amp;A. Forms 42 and 6 have been filed with the COGCC.                      A follow up on this site inspection needs to be conducted to ensure the                      compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	<p>silverr</p>	<p>05/02/2019</p>