

**Inspection Photos**  
**Location Name: Lewton Company F Unit 1**  
**Location ID: 001-08920**



**Pic 1**



**Pic 2**

**Inspection Photos**  
**Location Name: Lewton Company F Unit 1**  
**Location ID: 001-08920**



**Pic 3. Separator possible leak. Stained soil**



**Pic 4 possible leak stained soil.**



**Inspection Photos**  
**Location Name: Lewton Company F Unit 1**  
**Location ID: 001-08920**



**Pic 5 stained soil possible leak**



**Pic 6 separator berm appears to have burrowed through by animals.**



**Inspection Photos**  
**Location Name: Lewton Company F Unit 1**  
**Location ID: 001-08920**



**Pic 7 weeds on location.**



**Pic 8 unmarked risers in weeds.**



**Inspection Photos**  
**Location Name: Lewton Company F Unit 1**  
**Location ID: 001-08920**



**Pic 9 trash on location.**



**Pic 10 unmarked buried concrete vault.**

**Inspection Photos**  
**Location Name: Lewton Company F Unit 1**  
**Location ID: 001-08920**



**Pic 11 berm appears to have been burrowed through by animals.**



**Pic 11 berm appears to have been burrowed through by animals**