

Inspection Photos
Location Name: Comanche Creek 2-14
Location ID: 320321



Pic 1 weeds around motor house



Pic 2

Inspection Photos
Location Name: Comanche Creek 2-14
Location ID:



Pic 3 stained soil below counterweight.



Pic 4 what appears to be leak on pumping unit.

Inspection Photos
Location Name: Comanche Creek 2-14
Location ID:



Pic 5 weeds around wellhead.



Pic 6 stained soil below other counterweight.

Inspection Photos
Location Name: Comanche Creek 2-14
Location ID:



Pic 7 unknown barrel contents, no containment, appears to be leaking stained soil