FORM INSP

X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



All inspections

Inspection Date:

04/30/2019
Submitted Date:

04/30/2019
Document Number:

679703903

## FIELD INSPECTION FORM

Loc ID Inspector Name: 315252 Moran, Rick		On-Site	On-Site inspection		Status Summary:		
		2					
Operator Info	ormation:			X F	OLLOW UP INSPECTION REQUIRED		
OGCC Opera	itor Number:5	3255		<u> </u>	IO FOLLOW UP INSPECTION REQUIRED		
Name of Ope	rator: MARALEX RE	ESOURCES INC		<u>Find</u>	ings:		
				7	Number of Comments		
Address: P C	D BOX 338			1	Number of Corrective Actions		
City:	IGNACIO S	State: CO	Zip: 8113	<u>7</u>	orrective Action Response Requested		
				F	NY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE		
Contact Info	rmation:			•			
Contact Nan	ne	Phone	Email		Comment		
Graves, Jim		970-712-0099	mrinc20@qwes	toffice.net	Operations Manager		
Thompson, Bud			BLThomps@Bl	_M.gov			
COGCC, Engineering 303-89		303-894-2100	dnr coaccEngineering@state.				

Inc	pected	Facil	ItIDG.
1113	pecieu	ı acıı	ilico.

Reid, Jordan

Kellerby, Shaun

Pesicka, Conor

, Maralex

	<del></del>						
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230491	WELL	SI	01/01/2012	GW	103-08158	TRAIL CANYON-FEDERAL 1-2	SI

maralextechir@gmail.com

shaun.kellerby@state.co.us

conor.pesicka@state.co.us

co.us

aak@gvep.net

970-563-4000

970-858-8550

970-712-1248

970-415-0789

## **General Comment:**

**COGCC Inspection Report Summary.** 

On 4/30/2019 at approximately 11:00, inspector Rick Moran, conducted a follow up inspection at Maralex Resources well Trail Canyon Federal 1-2 in Rio Blanco county.

While there I conducted a follow up of:

- 1) FIR 675103155 from 12/7/2016
- 2) FIR 679702327 from 12/24/2018
- 3) FIR 679702848 from 2/1/2019
- 4) FIR 679703374 from 3/14/2019
- 5) warning latter document 401499076.


During this inspection the following possible compliance issues were observed as uncompleted:

- 1) Uncapped riser.
- 2) MIT.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703903.

<u>Location</u>						
Overall Good: X						
Signs/Marker:						
Туре	WELLHEAD					
Comment:						
Corrective Action:					Date	:
Emergency Contact N	lumber:					
Comment:	970-858-8550					
Corrective Action:					Date	
Overall Good: X						
Spills:						
Туре	Area	Volume				
In Containment: N	lo					
Comment:						
Multilple Spills a	and Releases?					
Equipment:						corrective date
Type: Horizontal Heat	ted Separator #	1				
Comment:						
Corrective Action:					Date:	
Type: Flow Line	#					
	Riser next to well head no	ot capped or	LOT	0.		
Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintgain in good mechanical condition per Rule 605.d.		Date:	01/28/2019			
Type: Deadman # & N	Type: Deadman # & Marked # 4					
Comment:						
Corrective Action:					Date:	
Type: Gas Meter Run	#	1				
Comment:						
Corrective Action:					Date:	
Type: Bird Protectors	#	1				
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No I	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Туре						
Comment:						
Corrective Action:					Date:	



	Inspected Facilities								
Facility ID:	230491	Type:	WELL	API Number:	103-08158	Status:	SI	Insp. Status:	SI
				<u>Idle V</u>	Vell				
Purpos	Purpose: X Shut In Temporarily Abandoned Reminder:								
<u>C</u>	omment:	No current MI	IT on record or	delinquent as requ	ired by Rule 326.				
		Last recorded	production De	ecember 2011. No N	MIT on file.				
Correctiv	e Action:							Date:	

Reclamation - Storm Water - Pit						
Storm Water:						
	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:	Comment: Erosion channel on the north edge of the location going into the creek. At time of inspection water was flowing from a culvert under Rio Blanco county road 27, across the edge of the location, into the channel, then into the creek.  The P&A marker for well Trail Canyon 1-2A is located 11 ft from the edge of the erosion					
channel.						
Corrective Action:		Date:				
Pits: X NO S	Pits: NO SURFACE INDICATION OF PIT					

## **Attached Documents**

You can go to COGCC Images (<a href="https://cogcc.state.co.us/weblink/">https://cogcc.state.co.us/weblink/</a>) and search by document number:

_					
Document Num	Description	URL			
402027586	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811228			
679703904	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811223			

Date Run: 5/7/2019 Doc [#679703903]