

Inspection Photos

API: 05-061-06471

Operator: MARATHON OIL COMPANY

Inspection Date: 5/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06471 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing north along the access road. The old road is has mostly turned into a two track. This area has been heavily used by cattle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06471 | Date: 5/15/2019

Inspection Photos



Photo 2. There is a riser shed at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06471 | Date: 5/15/2019

Inspection Photos



Photo 3. View of inside shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06471 | Date: 5/15/2019

Inspection Photos



Photo 4. There is a disconnected electric bos close to well coordinates.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06471 | Date: 5/15/2019

Inspection Photos



Photo 5. South of the location facing north. There is equipment in place.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06471 | Date: 5/15/2019

Inspection Photos



Photo 6. Approximately 300ft. West of the location is this pipe riser.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06471 | Date: 5/15/2019