

Inspection Photos
Location Name: Federal 6-25
API: 05-081-06745



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Federal 6-25
API: 05-081-06745



Photo 2. Sediment moving off location onto access road.



Photo 3. Erosion gully leaving location.

Inspection Photos
Location Name: Federal 6-25
API: 05-081-06745



Photo 4. Erosion gullies leaving location and transporting sediment onto access road.



Photo 5. Sediment migration on access road.

Inspection Photos
Location Name: Federal 6-25
API: 05-081-06745



Photo 6. Erosion gullies leaving location and transporting sediment towards drainage in background.



Photo 7. Sediment path of migration from location.