

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2019

Submitted Date:

05/14/2019

Document Number:

687904745**FIELD INSPECTION FORM**
 Loc ID 333566 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Azulai, .	970-563-4000	maralextech@gmail.com	all inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214932	WELL	SI	09/01/2017	GW	067-06537	SHELHAMMER 1	SI

General Comment:

Site inspection with photos at the end of this inspection report. Facility inspection for decommissioned compressor and dehydrator equipment for waste disposal and removal following this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Handwritten tank information posted on tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Contact information posted on sign.

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Sound panels from compression facility are sitting right next to separator and are being unused.		
Corrective Action:	Unused equipment needs to be removed from location per Rule 603.f.	Date:	06/16/2019
Type	WEEDS		
Comment:	Weeds surrounding wellhead and separator need to be controlled.		
Corrective Action:	Control weeds to comply with Rule 603.f.	Date:	06/16/2019
Type	TRASH		
Comment:	Trash in meter house that is infested with mice and packrats needs to be removed.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/16/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Located in meter house.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Bradenhead plumbed to surface.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 3			
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to gathering system.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Appears berm capacity will not hold volume of one tank plus stormwater/rain event. Berm should be built up to reflect proper secondary containment volumes. Control weeds in secondary containment.			
Corrective Action:	Raise berm to comply with Rule 906.d.(1) and Rule 605.a.(4) and Control weeds to comply with Rule 603.f.			Date: 06/16/2019

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	214932	Type:	WELL	API Number:	067-06537	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Shut in and not producing. No LOTO on wellhead or separator or meter tube.									
Corrective Action: Produce well after performing successfull Mechanical integrity test or plug and abandoned well.									
Date: 05/15/2019									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402046699	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825268
687904795	SHELHAMMER 1 Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825260