

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2019

Submitted Date:

06/05/2019

Document Number:

696600064

FIELD INSPECTION FORM

Loc ID 312609 Inspector Name: Wentzel, Dougo On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
16 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Peicka, Conor		conor.pesicka@state.co.us	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Graves, Jim		mrinc20@qwestoffice.net	
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222011	WELL	SI	05/01/2012	GW	077-08613	SOUTH SHALE RIDGE 7-24	SI

General Comment:

This is a follow up inspection from Doc#689401339 dated 6/7/18 and 675001726 dated 1/9/19, and 675002096 dated 3/29/19 . Required Corrective Action (s) items noted in previous inspections have not all been satisfied.

Location			
Lease Road:			
Type	Access		
comment:	Access road is being maintained. Blade on access road during inspection.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank label has been updated. Corrective action has been made		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign has been placed at wellhead Corrective action has been made		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery sign on location		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	07/05/2019
Emergency Contact Number:			
Comment:	970-858-8550 / 911 Lettering fading on wellhead sign		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused equipment or trash stored on location		
Corrective Action:	Comply with Rule 603.f .	Date:	07/05/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		
Comment:	Fiberglass open top				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 222011 Type: WELL API Number: 077-08613 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in, Well last produced April 2010. MIT on 2/19/2015 Doc#400797603.
No current MIT on file

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 06/17/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion not being controlled on the location at this time. BMP's not in place or maintained. Sediment running onto and off location causing erosion see inspection 675002096 dated 3/29/19</p>						Date: 04/29/2019
<p>Corrective Action: Install or repair required BMPs per Rule 1002.f.</p>						
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

COGCC Comments

Comment	User	Date
<p>On Tuesday (Date 06/4/2019) at approximately (1338), I, Inspector Dougo Wentzel, conducted a This is a follow up inspection from doc#675002096 Dated 3/29/19 at (Maralex) (Shale Ridge 7-24), at (API #077-08613) in (Mesa, county) Colorado.</p> <p>While there, I observed a (Production location operation only) During this inspection the following possible compliance issues were observed: No Battery sign posted on location Unused equipment or trash stored on location Stormwater BMP's are not in place No current MIT on file., (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402066456	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841953
696600065	Inspection 696600064 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841945