

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2019

Submitted Date:

07/16/2019

Document Number:

679704741

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
314960 _____ Moran, Rick _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Jordan	970-563-4000	maralextechjr@gmail.com	All inspections
, Maralex	970-858-8550	aak@gvep.net	
Graves, Jim	970-712-0099	mrinc20@qwestoffice.net	Operations Manager
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229980	WELL	PR	09/07/1995	GW	103-07639	SOLDIER CANYON 26-1	PR

General Comment:

COGCC Inspection Report Summary.

On 7-16-2019 at approximately 17:15, inspector Rick Moran, conducted a follow up inspection at Maralex Resources well Soldier Canyon 26-1 in Rio Blanco county of FIR document 679702276.

The following compliance issues were observed as uncompleted:

- 1) Battery sign incomplete. Photo 2. Complete by 2-22-2019.

Additional compliance issues were identified:

- 1) Missing well head sign. Photo 3. Complete by 9-13-2019.
2) Gas leak in separator building. Photo 4. Complete by 8-15-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704741.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Well head sign not present.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/13/2019
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battey. Missing nearest public road and "911".		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/22/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Bird Protectors		1		
Comment:				
Corrective Action:				Date:
Gas Meter Run		1		
Comment:				
Corrective Action:				Date:
Deadman # & Marked		3		
Comment:				
Corrective Action:				Date:
Horizontal Heated Separator		1		
Comment:	Gas smelled while standing on the side of the separator nearest the blowdown tank. No smell of gas next to the blowdown tank.			

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date: <u>08/15/2019</u>
---	-------------------------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		39.661010,-108.703740
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	90 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 229980 Type: WELL API Number: 103-07639 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action: _____ Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: _____ Lat: 39.673180 Long: -108.699590

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Fencing:

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment: _____

Corrective Action _____ Date: _____

Netting:

Netting Type: Fence/Net Combo Netting Condition: Good

Comment: _____

Corrective Action _____ Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402111886	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880876
679704742	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880872