

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2019

Submitted Date:

07/16/2019

Document Number:

687905188**FIELD INSPECTION FORM**Loc ID 325967 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	<a href="#">e-mail receipient</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215648	WELL	PR	10/01/2018	OW	067-07253	DYE HARD 8	PR

**General Comment:**[Site inspection with photos at the end of this inspection report.](#)

Location					
<b>Lease Road:</b>					
Type	Access				
comment:	Two-track dirt road.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Tank labels and placards missing on crude oil storage tank. Sign or label not posted or information inaccurate on tanks or containers				
Corrective Action:	Install labels to comply with Rule 210.d.				Date: 08/16/2019
Type	WELLHEAD				
Comment:	Sign posted at wellhead.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Contact information posted on sign.				
Corrective Action:					Date: _____
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
Type: Ancillary equipment	# 1				corrective date
Comment:					
Corrective Action:					Date:
Type: Flow Line	# 2				
Comment:	1-2" flowline from wellhead to crude oil storage tank. 1-1" flowline from wellhead to pumpjack engine fuel gas.				
Corrective Action:					Date:
Type: Pump Jack	# 1				
Comment:					
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:	Engine oil is staining the soil below it as well as staining the eastern side along the pumpjack.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.				Date: 08/16/2019
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLS	STEEL AST		,

Comment:	Missing labeling on tank. See CA under signs and markers tab.		
Corrective Action:		Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>				
Facility ID: 215648	Type: WELL	API Number: 067-07253	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402111714	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880625">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880625</a>
687905195	Stained soil around engine.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880613">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880613</a>
687905196	Missing tank labels.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880614">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4880614</a>