

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2019

Submitted Date:

08/22/2019

Document Number:

689802937

FIELD INSPECTION FORM

Loc ID 312978 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 82440
Name of Operator: STEHLE OIL COMPANY
Address: P O BOX 1577
City: CRAIG State: CO Zip: 81626

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|----------------|----------------------------------|---------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Stehle, Cary | (970) 824-6909 | carystehle@gmail.com | |
| | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 223139 | WELL | SI | 01/27/2014 | OW | 081-06501 | ILES DOME 3 | TA |

General Comment:

[COGCC Inspection Report 689802937 Summary](#)
On Monday 07/15/2019 at approximately 11:30, I, Inspector Emily Waldron, conducted a field inspection at Stehle Oil Company Iles Dome 3, at 05-081-06501 in Moffat County Colorado. While there, I performed a follow up inspection to inspection report 689801292 and warner letter document number 401965974. No corrective actions have been performed.

Location

| | | | |
|--------------------|---|-------|------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Road overgrown and extremely difficult to locate. | | |
| Corrective Action: | Maintain road. | Date: | 09/20/2019 |

Overall Good:

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|--------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | 970-824-6909 | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Flowline risers not LO/TO or marked are considered unused equipment 1 - 2" steel riser observed at wellhead not marked for abandonment or locked out tagged out. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 01/11/2018 |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 223139 Type: WELL API Number: 081-06501 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689803004 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916771 |