

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2019

Submitted Date:

08/16/2019

Document Number:

696600499

**FIELD INSPECTION FORM**

Loc ID 334465 Inspector Name: Wentzel, Dougo On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 25 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297911	WELL	PR	06/09/2008	GW	077-09710	NVEGA 22-344	PR
297912	WELL	PR	04/01/2019	GW	077-09711	NVEGA 22-334	PR
297913	WELL	PR	08/22/2008	GW	077-09712	NVEGA 22-341	PR
297914	WELL	PR	08/22/2008	GW	077-09713	NVEGA 22-221	PR
297915	WELL	PR	08/22/2008	GW	077-09714	NVEGA 22-321	PR
297916	WELL	PR	04/01/2019	GW	077-09715	NVEGA 22-324	PR
297917	WELL	PR	08/22/2008	GW	077-09716	NVEGA 22-224	PR
297918	WELL	PR	04/01/2019	GW	077-09717	NVega 22-234	PR
297919	WELL	PR	08/22/2008	GW	077-09718	NVEGA 22-241	PR
297920	WELL	PR	08/31/2015	GW	077-09719	NVEGA 22-231	PR
297921	WELL	PR	08/22/2008	GW	077-09720	NVEGA 22-244	PR
297922	WELL	PR	04/01/2019	GW	077-09721	NVEGA 22-331	PR
300706	WELL	PR	09/28/2012	GW	077-09912	NVEGA 2B-22-233D	PR

**General Comment:**

[Routine FIU General Field Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil on location by separators. See photos 10,11		
Corrective Action:	Comply with Rule 603.f .		Date: <u>08/26/2019</u>
Type	TRASH		
Comment:	Trash on location. See photos 12,13		
Corrective Action:	Comply with Rule 603.f .		Date: <u>08/26/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 13		
Comment:			

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 13		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:	Methonal tank needs labels, Faded hard to read.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: <a href="#">See under condensate tanks</a>					Date:	
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	400 BBLs	STEEL AST		,	
Comment:					Date:	
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: <a href="#">Holes in tank containment liner. See photos 6 through 9</a>				
Corrective Action: <a href="#">Repair or install berms or other secondary containment devices per Rule 605.a.(4).</a>				Date: <u>08/26/2019</u>

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	297911	Type:	WELL	API Number:	077-09710	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	297912	Type:	WELL	API Number:	077-09711	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	297913	Type:	WELL	API Number:	077-09712	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	297914	Type:	WELL	API Number:	077-09713	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	297915	Type:	WELL	API Number:	077-09714	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	297916	Type:	WELL	API Number:	077-09715	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				
Facility ID:	297917	Type:	WELL	API Number:	077-09716	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:					Date:				

Corrective Action:		Date:	
--------------------	--	-------	--

Facility ID: <u>297918</u>	Type: <u>WELL</u>	API Number: <u>077-09717</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment:	<a href="#">Producing Well</a>	
Corrective Action:		Date:

Facility ID: <u>297919</u>	Type: <u>WELL</u>	API Number: <u>077-09718</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment:	<a href="#">Producing Well</a>	
Corrective Action:		Date:

Facility ID: <u>297920</u>	Type: <u>WELL</u>	API Number: <u>077-09719</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment:	<a href="#">Producing Well</a>	
Corrective Action:		Date:

Facility ID: <u>297921</u>	Type: <u>WELL</u>	API Number: <u>077-09720</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment:	<a href="#">Producing Well</a>	
Corrective Action:		Date:

Facility ID: <u>297922</u>	Type: <u>WELL</u>	API Number: <u>077-09721</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment:	<a href="#">Producing Well</a>	
Corrective Action:		Date:

Facility ID: <u>300706</u>	Type: <u>WELL</u>	API Number: <u>077-09912</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment:	<a href="#">Producing Well</a>	
Corrective Action:		Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Waddles	Pass					
Sediment Traps	Pass					
		Culverts	Pass			
Drains	Fail					
Retention Ponds	Pass					
Seeding	Fail					
Rip Rap	Pass					
Compaction	Pass					
Gradient Terraces	Fail					
		Ditches	Pass			
Berms	Fail					
		Check Dams	Pass			
		Gravel	Pass			
		Compaction	Pass			
Culverts	Pass					
Gravel	Pass					

**Comment:** Stormwater erosion not being controlled on the location at this time. BMP's not in place, need repaired or are not being maintained at this time. Erosion is evident along un-stabilized slope on the South side of location. Erosion sediment moving off slope and choking out vegetation. See Photos 14 through 17 and 24 through 29  
 Drain pipe is being used as a BMP and is in need of maintenance. See photos 18,19. Lined ditch on the West side of location, is being used as a BMP and is in need of maintenance. See photos 20,21.  
 Erosion sediment is moving off un-stabilized slope on the west side of location below the berm, and is choking out vegetation. See photos 22,23.

**Corrective Action:** Install or repair required BMPs per Rule 1002.f.

**Date:** 09/16/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Thursday) (8/15/19) at approximately (1305)                      I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection)                      at (Laramie) (NVEGA 22-341), (API #077-09712) in (Mesa) Colorado.                      While there, I observed (A Production Operation only.)                      During this inspection compliance issues were observed:                      Holes inside of containment liner. See photos 6 through 9.                      Stained soil and gravel by separators. See photos 10 and 11.                      Trash left on location. See photos 12 and 13.                      Stormwater issues were observed:                      BMP's not in place, need repaired or are not being maintained at this time.                      Erosion is evident along un-stabilized slope on the South side of location. Erosion sediment                      moving off slope and choking out vegetation. See Photos 14 through 17 and 24 through 29.                      Drain pipe is being used as a BMP and is in need of maintenance. See photos 18,19.                      Lined ditch on the West side of location, is being used as a BMP and is in need of                      maintenance. See photos 20,21.                      Erosion sediment is moving off un-stabilized slope, on the west side of location below the                      berm, and is choking out vegetation. See photos 22,23.</p> <p>(Refer to Corrective Action Matrix for comments, corrective actions, and corrective action                      date). Refer to photograph of observed. compliance issue.                      A follow up on this site inspection will be conducted to ensure the compliance issues have                      been corrected to comply with COGCC Rules.                      (if correction actions are identified)                      This is a summary of inspection report.</p>	wentzeld	08/16/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402146956	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4911401">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4911401</a>
696600500	Inspection 696600499 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4911398">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4911398</a>