

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2019

Submitted Date:

08/16/2019

Document Number:

696600507**FIELD INSPECTION FORM**
 Loc ID 312634 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:           
**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222064	WELL	PR	09/01/2017	GW	077-08666	OXBOW 18-1E	PR

**General Comment:**

This is a follow up from inspection dated 7/8/2019 Doc# 696600266 Required Corrective Action (s) items noted in previous inspections have been satisfied.

Battery sign has been placed at entrance.

Hole over culvert has been repaired.

Trash on location has been removed.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Erosion sediment moving down access road. BMP.s need maintentance. See corrective action in Stormwater section of inspection.		
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 0		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment:	80bbls					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	222064	Type:	WELL	API Number:	077-08666	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p><b>Comment:</b> Stormwater erosion not being controlled on the location or access rd at this time. BMP's not in place, need repaired or are not being maintained at this time. Sediment is moving onto or off location on the N and NE and S sides of location. BMP's need maintenance. Sediment is choking out vegetation. See photos. 6-9 Erosion sediment moving off location into a sediment trap and through the armoring. Sediment trap is on the S side of location, BMP needs maintenance. See photos 10,11. Photo on S side of location. Erosion sediment is moving off location and choking out vegetation. See photos 12,13. Erosion sediment moving onto location by tank battery. BMP not working and needs maintenance at time of inspection. See photos 14,15</p> <p><b>Corrective Action:</b> Install or repair required BMPs per Rule 1002.f.</p>						<p><b>Date:</b> 09/17/2019</p>
<p><b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**COGCC Comments**

Comment	User	Date
<p>On (Friday) (8/16/19) at approximately (1303), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field re-Inspection) at (Laramie) (Oxbow 18-1E), (API #077-08666) in (Mesa) Colorado. While there, I observed (A Production Operation only.) Corrective actions from previous inspection have been made: Battery sign has been posted at entrance. Unused equipment stored on location has been removed. Trash can has been removed. Culvert has been repaired or replaced. During this inspection compliance issues were observed: Stormwater erosion not being controlled on the location at this time. BMP's not in place, need repaired or are not being maintained at this time. Sediment is moving onto or off location on the N, NE and S sides of location. BMP's need maintenance. Sediment is choking out vegetation. See photos. 6-9 Erosion sediment is moving off location into a sediment trap and through the armoring. Sediment trap is on the S side of location, and needs maintenance. See photos 10,11. Photo is of the S side of location. Erosion sediment is moving off location and choking out vegetation. See photos 12,13 Erosion sediment moving onto location by tank battery. BMP not working and needs maintenance at time of inspection. See photos 14,15 Sediment is moving down access road. BMP's not in place or need maintenance. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/16/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402147779	INSPECTION SUBMITTED	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4912058">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4912058</a>
696600508	Inspection 696600507 photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4912054">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4912054</a>