



Federal 11-90-35 #1 —API—051-06059 - Inspection Doc 693900462 -6/19/19

CA #1 of 1—Repair/replace erosion control blanket, additional slope stabilization measures are needed on all well pad cut-slopes.

Erosion Control Blankets acted as designed and have been removed. Additional slope stabilization measures were added.