

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2019

Submitted Date:

08/28/2019

Document Number:

696101237**FIELD INSPECTION FORM**
 Loc ID 306508 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289303	WELL	PR	06/01/2019	OW	123-24807	WILHITE 30-34	SI

General Comment:

This is a WELL inspection.
Well is Shut-In | SI.
Battery: Inactive.
Centralized Battery serves 2 Location IDs (310319, 306508).
(2: wells ; Shut-In | SI).

Refer to Field Inspection Doc. #696101235 and/or Location ID #310319 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/09/2019. See photo #1.		
Corrective Action:	Remove, manage, & control weeds around wellsite. Comply with Rule 603.f.		Date: 09/09/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	Refer to Field Inspection Doc. #696101235 and/or Location ID #310319 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment:	Appears plumbed to surface.		Date:	
Corrective Action:			Date:	
Type:		#		
Comment:	Refer to Field Inspection Doc. #696101235 and/or Location ID #310319 for Battery / Facility, Equipment info.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.540096,-104.592901
Comment:	Centralized Battery serves 2 Location IDs (310319, 306508). Refer to Field Inspection Doc. #696101235 and/or Location ID #310319 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 289303 Type: WELL API Number: 123-24807 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI. Observed Hi/Lo motor valve closed at separator.
COGCC records indicate last Prod: 06/2019.
Form 21 Doc #401814562, Approved MIT done: 10/23/2018.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 08/27/2019 at approximately 12:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WILHITE-67N64W /30SESW Location ID: 306508 Well Name: Wilhite 30-34 API: 05-123-24807 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s) - 1: Shut-In SI. Hi/Lo motor valve shut at separator. Battery: Inactive Centralized Battery serves 2 Location IDs (310319, 306508). (2: wells ; Shut-In SI).</p> <p>Refer to Field Inspection Doc. #696101235 and/or Location ID #310319 for Battery / Facility, Equipment info.</p> <p>1: Corrective Actions observed. 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/09/2019. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/28/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402160083	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4923352

696101238	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4923351
-----------	-------------	---

