

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2019

Submitted Date:

09/11/2019

Document Number:

679705393**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 314726      Moran, Rick      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON USA INCCity: RANGELY      State: CO      Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Sanford, Anita		atlx@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229417	WELL	PR	01/01/1999	OW	103-07072	WEYRAUCH 4 X36	PR

**General Comment:**COGCC Inspection Report Summary.On 9-10-2019 at approximately 17:30, inspector Rick Moran, conducted a routine inspection at Chevron well Weyrauch 4X36 in Rio Blanco county.During this inspection the following compliance issues were observed:1) Stained soil next to pump jack. Photos 2, 3, 4. Complete by 10-11-2019.A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.This is a summary of inspection report 679705393.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil next to pump jack.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/11/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	229417	Type:	WELL	API Number:	103-07072	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pump jack idle at time of inspection.								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705394	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934479">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934479</a>