

Inspection Photos

API: 05-061-06293

Operator: CHEMCO INC

Inspection Date: 10/7/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

Inspection Photos



Photo 2. Well sign is posted at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

Inspection Photos



Photo 3. The berm around the tank is degraded and not sufficient to contain a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

Inspection Photos



Photo 4. Pipe risers at the location have no LO/TO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

Inspection Photos



Photo 5. Facing west toward the wellhead. The area northeast of the well is bare of vegetation and appears to be a result of a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

Inspection Photos



Photo 6. Facing north at the location which appears to have been impacted by a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

Inspection Photos




Photo 7. View of aerial image shows area north of the location bare of vegetation which may be the result of a former spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019