

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

10/06/2019

Document Number:

688305871

**FIELD INSPECTION FORM**

Loc ID 317088 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 76830  
Name of Operator: SCHMID PROPERTIES INC  
Address: PO BOX 389  
City: HICO State: TX Zip: 76457

**Findings:**

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schmid, William	337-261-1500	tenniswilliam123@cs.com	
Walker, Carolyn	254-796-2100	schmidprop@gmail.com	
Sutphin, Dirk		dirk.sutphin@state.co.us	COGCC Engineer

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236071	WELL	PR	06/04/1971	OW	121-08561	CLARK 8-35	PR

**General Comment:**

Routine Inspection

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 377-261-1500 and 970-554-1988 (check that all emergency contact numbers are current)

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	wire panels		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	bermed, propane		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:	
Corrective Action:	Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	Open Top		,
Comment: <span style="color:blue;">netted on top</span>					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <span style="color:blue;">same berms as crude oil tank</span>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:			Date:	

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:			Date:	

**Location Construction**

Location ID: 236071 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** No COAs.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: 236071 Type: WELL API Number: 121-08561 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR. Jun 2019 production reported to COGCC database. There is a gap in reported production between Jun 2008 and Mar 2012-contact COGCC Engineering.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: None      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: None      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition: \_\_\_\_\_

<b>Comment:</b>		<b>Date:</b>
<b>Corrective Action</b>		
<b>Anchor Trench Present:</b>	<b>Oil Accumulation:</b> <u>NO</u>	<b>2+ feet Freeboard:</b> <u>YES</u>
<b>Comment:</b>		
<b>Corrective Action</b>		<b>Date:</b>
<b>Type:</b> <u>Skimming/Settling</u>	<b>Lined:</b> <u>NO</u>	<b>Pit ID:</b>
	<b>Lat:</b>	<b>Long:</b>
<b>Reference Point:</b> _____	<b>Other:</b> _____	<b>Length:</b> _____
		<b>Width:</b> _____
<b>Lining:</b>		
<b>Liner Type:</b>	<b>Liner Condition:</b>	
<b>Comment:</b>		
<b>Corrective Action</b>		<b>Date:</b>
<b>Fencing:</b>		
<b>Fencing Type:</b> <u>None</u>	<b>Fencing Condition:</b>	
<b>Comment:</b>		
<b>Corrective Action</b>		<b>Date:</b>
<b>Netting:</b>		
<b>Netting Type:</b>	<b>Netting Condition:</b>	
<b>Comment:</b>		
<b>Corrective Action</b>		<b>Date:</b>
<b>Anchor Trench Present:</b>	<b>Oil Accumulation:</b> <u>YES</u>	<b>2+ feet Freeboard:</b> <u>YES</u>
<b>Comment:</b>	<u>Oil on skim pit, not netted. Fix hole in fiberglass tank (see attached photo). Check that vent pipe in tank has bird cover.</u>	
<b>Corrective Action</b>	<u>Pumper was contacted on day of inspection and sent truck to clean oil from pit. Inspector needs to reinspect.</u>	
		<b>Date:</b> <u>09/25/2019</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402200881	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956156</a>
688305961	Schmid Properties Clark 8-35	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956148">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956148</a>