

Inspection Photos

Location Name: FIRWHAWK 34-26 FOLLOWUP

API#: 05-071-08389

INSP. #: 695101752



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: FIRWHAWK 34-26 FOLLOWUP

API#: 05-071-08389

INSP. #: 695101752



PHOTO 3: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. 12-03-19