

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2019

Submitted Date:

11/19/2019

Document Number:

696101578**FIELD INSPECTION FORM**Loc ID 331380 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261349	WELL	PA	01/14/2019	GW	123-20593	DOW 23-28	PA

General Comment:[This is a PLUGGED & ABANDONED WELL & BATTERY inspection.](#)[Well\(s\): 1: Plugged & Abandoned | PA.](#)[Battery: Abandoned. Most equipment removed.](#)[Reclamation progressing.](#)[Abandoned Battery SE corner GPS coordinates: 40.367820, -104.445356.](#)

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (Automation controls & tower) at Abandoned Battery site. Refer to Rule 603.f. See photo #2.		
Corrective Action:	Remove unused equipment (Automation controls & tower) at Abandoned Battery site. Comply w/ Rule 603.f. See photo #2.		Date: 12/04/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 0		corrective date
Comment:	Abandoned Well & Battery.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:			Date:
Type: Pig Station	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Automation controls & tower remain at Abandoned Battery site.		
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 0		

Comment: Abandoned Well & Battery.		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 0	
Comment: Abandoned Well & Battery.		Date:
Corrective Action:		Date:
Type: Emission Control Device	# 0	
Comment: Abandoned Well & Battery.		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment: Abandoned Well & Battery.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment: Abandoned Well & Battery.					
Corrective Action:					
Date:					

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
--------	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	261349	Type:	WELL	API Number:	123-20593	Status:	PA	Insp. Status:	PA
Workover									
Comment:		Plugged & Abandoned PA. Casing appears to be cut / capped. Form 6 doc. #401914739 indicates cut & cap date: 01/14/2019.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 11/18/2019 at approximately 16:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: Dow /23-28 Pad Location ID: 331380 Well Name: DOW 23-28 API: 05-123-20593 Location County: Weld County, Colorado Weather: Overcast & Dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. Most equipment removed. Reclamation progressing.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.367820, -104.445356.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Unused equipment (Automation controls & tower) at Abandoned Battery site. Refer to Rule 603.f. Remove unused equipment (Automation controls & tower) at Abandoned Battery site. Comply w/ Rule 603.f. Corrective Action date: 12/04/2019. See photo #2.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/19/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101579	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992316