

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2020

Submitted Date:

01/09/2020

Document Number:

699300886

**FIELD INSPECTION FORM**

Loc ID 318279 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241028	WELL	PR	05/01/2019	OW	123-08816	TOM L. RUSSELL 2	PR
453783	TANK BATTERY	AC	01/19/2018		-	Russell, Tom battery	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	stained soil between crude oil tanks and by heated horizontal separator & inside FWKO housing		
Corrective Action:	Comply with Rule 907.e	Date:	01/24/2020
Type	TRASH		
Comment:	bent rebar by electric panel area		
Corrective Action:	Comply with 603.f	Date:	01/16/2020
Type	DEBRIS		
Comment:	Dead weeds around wellsite		
Corrective Action:	Comply with Rule 603.f	Date:	01/16/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment:	Chain link		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric panel area steel pipe		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: FWKO	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel, transformers and meterbox		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	#		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate

Comment:		
Corrective Action:		Date:

**Wells Served By Facilities Above****AirsID**

API Number

API Number

AirsID

123-07523

123-08816

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241028 Type: WELL API Number: 123-08816 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 453783 Type: TANK API Number: - Status: AC Insp. Status: AC

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 1/9/2020 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Tom L. Russell #2 at API #05-123-08816 in Weld County Colorado.</p> <p>While there, I observed producing wellsite &amp; tank battery. During this inspection the following compliance issues were observed: 603.f housekeeping: dead weeds around wellsite &amp; tank battery, CA date 1/16/2020 see photos 2 and 3 TB pics 3 &amp; 4. 603.f housekeeping: Trash(bent rebar) by electric panel area, CA date 1/16/2020 see photo 4. 907.e housekeeping: stained soil between crude oil tanks and by separator and inside FWKO housing, CA date 1/24/2020 see TB photos 6 &amp; 7. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	01/09/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402281402	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032869">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032869</a>
402281435	tank battery pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032918</a>
699300887	wellsite pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032865">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032865</a>