

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2020

Submitted Date:

02/02/2020

Document Number:

679707189**FIELD INSPECTION FORM**Loc ID 316453 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10384Name of Operator: GENESIS GAS & OIL COLORADO LLCAddress: 1660 LINCOLN ST STE 2100City: DENVER State: CO Zip: 80246**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Kimmel, March	210-363-2859	mkimmel@headwatersexp.co m	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277276	WELL	SI	03/01/2017	GW	103-10561	CRU 4401D A23 1N100	TA

General Comment:COGCC Inspection Report Summary.On 1-31-2020 at approximately 15:30, inspector Rick Moran, conducted a follow up inspection at Genesis Gas & Oil well Calamity Ridge Unit 4401D A23 1N100 in Rio Blanco county of FIR document:1) 679704921, dated 7-30-2019.Additional compliance issues:1) Pump jack weed debris. Photos 12 & 13. Complete by 3-1-2020.The following compliance issues are uncompleted:

- 1) Tank label incomplete. Photo 3. Complete by 9-30-2019.
- 2) Tank liner holes. Photo 4 & 5. Complete by 8-30-2019.
- 3) Unmarked deadman. Photos 6 & 7. Complete by 8-23-2019.
- 4) Missing valve can cover. Photos 8 & 9. Complete by 8-30-2019.
- 5) Battery sign missing "911". Photos 10 & 11. Complete by 9-30-2019.
- 6) Missing well head sign. Photos 14 & 15. Complete by 9-30-2019.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.This is a summary of inspection report 679707189.

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	No well head sign present.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/30/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing operator name & capacity.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/30/2019

Emergency Contact Number:			
Comment:	Battery sign missing "911".		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/30/2019

Good Housekeeping:			
Type	DEBRIS		
Comment:	Weed debris around pump jack.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/01/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 3			
Comment:	One unmarked deadman.			
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	08/23/2019
Type: Other	# 1			

Comment:	Valve can missing cover.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/30/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		40.046100,-108.575900	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal				Inadequate	
Comment:	8 areas with holes in liner.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).				Date: 08/30/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 277276 Type: WELL API Number: 103-10561 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last recorded production December 2012. Last MIT on 7-14-2015.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402300973	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055212
679707190	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055198