

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2020

Submitted Date:

02/10/2020

Document Number:

699101052**FIELD INSPECTION FORM**

Loc ID 422923 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422937	WELL	SI	04/01/2019	OW	123-33453	FRENCH LAKE 3-62-6 1H	SI

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Placards "NFPA" not legible on water tanks. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	02/19/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: <input style="width: 100px;" type="text"/>

Good Housekeeping:			
Type	TRASH		
Comment:	Trash around pumping unit, inside containment for production tanks & in building for vertical separator needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/19/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment around pumping unit, inside containment for production tanks & in building for vertical separator needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/19/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment: Appears to be plumbed to surface.		Date:
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Natural gas ran engine		Date:
Corrective Action:		Date:
Type: Progressive Cavity	# 1	
Comment: Recycle pump		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: Meter that shows what they have sent to the ECD		Date:
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment: Shares containment with crude oil tanks.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST		40.248690,-104.375130
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 422937 Type: WELL API Number: 123-33453 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 2/10/20 at approximately 0817 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at French Lake 3-62-6 1H of Bonanza Creek Energy, at Location # 422937 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Trash around pumping unit, inside containment for production tanks & in building for vertical separator needs to be removed for good housekeeping. Comply with Rule 603.f . With a corrective action date of 2/19/20.</p> <p>Unused Equipment around pumping unit, inside containment for production tanks & in building for vertical separator needs to be removed for good housekeeping. Comply with Rule 603.f . With a corrective action date of 2/19/20.</p> <p>Placards "NFPA" not legible on water tanks. Install sign to comply with Rule 210.e. With a corrective action date of 2/19/20.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p>	burnsa	02/10/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402308431	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5062836
699101053	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5062826