

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2020

Submitted Date:

02/10/2020

Document Number:

699101068**FIELD INSPECTION FORM**Loc ID 453242 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------------------------------|
| , | | EHSRC@bonanzacrk.com | All Inspections |
| Pesicka, Conor | | conor.pesicka@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 453241 | WELL | PR | 05/01/2018 | | 123-46001 | Mustang V41-34-33XRLNB | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Remove or remediate stained soil around production tanks/ load out line. See attached photos | | |
| Corrective Action: | "Properly treat or dispose of oily waste in accordance with 907.e." | Date: | 03/02/2020 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused Equipment around pumping unit needs to be removed for good housekeeping. See attached photos | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 03/02/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | | |
|-----------------------------------|-----------------------------------|--|--|-----------------|
| Equipment: | | | | corrective date |
| Type: Emission Control Device | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | # 1 | | | |
| Comment: | Appears to be plumbed to surface. | | | |
| Corrective Action: | | | | Date: |
| Type: Vertical Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | Meters gas going to the ECD | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heater Treater | # 1 | | | |
| Comment: | Used for heat trace. | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bird Protectors | # 2 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Pump Jack | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Prime Mover | # 1 | | | |
| Comment: | Natural Gas Engine | | | |
| Corrective Action: | | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 500 BBLS | STEEL AST | | , |
| Comment: | Shares containment with crude oil tanks. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | |
|------------------|----------|--|--|--|
| Condition | Adequate | | | |
| Other (Content) | | | | |
| Other (Capacity) | | | | |
| Other (Type) | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|--|
| | | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| CRUDE OIL | 3 | 500 BBLS | STEEL AST | | 40.271130,-104.416340 | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Paint

| | | | | | | | |
|------------------|----------|--|--|--|--|--|--|
| Condition | Adequate | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |

Berms

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 453241 Type: WELL API Number: 123-46001 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday 2/10/20 at approximately 1344 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Mustang 42-34 Pad of Bonanza Creek Energy, at Location # 453242 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Remove or remediate stained soil around production tanks/ load out line. "Properly treat or dispose of oily waste in accordance with 907.e." With a corrective action date of 3/2/20</p> <p>Unused Equipment around pumping unit needs to be removed for good housekeeping.</p> <p>Comply with Rule 603.f . With a corrective action date of 3/2/20.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p> | burnsa | 02/10/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402308439 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5062844 |
| 699101071 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5062834 |