

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2020

Submitted Date:

03/02/2020

Document Number:

688307069**FIELD INSPECTION FORM**Loc ID 316944 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	COGCC Field Inspection QA
Chisholm, Jim	405-642-9437	investmentequipment@gmail.com	All Inspections
Highberger, Kathryn	(970) 867-9007	dkama@kci.net	Designated Agent
Young, Rob		rob.young@state.co.us	COGCC EPS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233377	WELL	PR	11/06/1963	OW	121-05413	DAVIS W T 1	PR

General Comment:Pit Spill Inspection.

Produced water spilled from NE corner of east pit berms due to an animal hole. Spill then ran SE through winter wheat field then directly south into fallow wheat field ~1 mile. Observed pit water level had dropped ~3 ft and pit is ~220'x110'. Backhoe operator was on location at time of inspection filling in the hole in the berm. Inspector contracted operator by phone and asked operator to check and maintain berms for other animal holes that were observed in the pit berms at the time of inspection. Inspector contacted COGCC EPS also on 2/28/2020. See attached photos.

Form 19 I was in process on 2/28/2020. Corrective action is to contact COGCC EPS.

Inspected Facilities									
Facility ID:	233377	Type:	WELL	API Number:	121-05413	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: 30.000000Long: -103.128120Reference Point: NEOther: 3' drop in pit levelLength: 220Width: 110**Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: NE corner of east pit berms broke due to an animal hole per operator. Backhoe was on location fixing the hole in the berm at time of inspection.Corrective Action: Contact COGCC EPS.Date: 03/03/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402328912	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082589
688307070	Investment Equipment Davis W T 1 Spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082588