

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2020

Submitted Date:

03/02/2020

Document Number:

688307098

FIELD INSPECTION FORM

Loc ID 317095 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10691
Name of Operator: PHOENIX RESOURCES LLC
Address: 5566 S SYCAMORE STREET
City: LITTLETON State: CO Zip: 80120

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|---------------------------|---------|
| Heffner, Taylor | 303-219-3362 | theffner@phxresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 236181 | WELL | PR | 02/16/1972 | OW | 121-08671 | ATKINSON-CHENOWETH 4 | PR |

General Comment:

[Routine Inspection](#)
[Update Form 7s. Animal hole on SE corner of tank berms.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | # | | corrective date |
|-------------------------|----------|-------|-----------------|
| Prime Mover | # 1 | | |
| Comment: | electric | | |
| Corrective Action: | | Date: | |
| Vertical Heater Treater | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|
| | | | | | |

| | | | | | |
|--------------------|---|----------|----------------|--|-------|
| PRODUCED WATER | 1 | 200 BBLs | PBV FIBERGLASS | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Earth | Adequate | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|--|---------------------|---------------------|-------------|------------------|
| Earth | | | | Inadequate | |
| Comment: | Animal holes in berms (see attached photo). | | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 906.d.(1). | | | | Date: 03/06/2020 |

Venting:

| | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 236181 Type: WELL API Number: 121-08671 Status: PR Insp. Status: PR

Producing Well

Comment: [PR. Aug 2019 production last reported to COGCC database. Update Form 7s.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: None Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 402329375 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5083122 |
| 688307107 | Phoenix Resources Atkinson-Chenoweth 4 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5083118 |