

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/06/2020

Submitted Date:

03/06/2020

Document Number:

700400355

FIELD INSPECTION FORM
 Loc ID 315205 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 3975

Name of Operator: ARGALI EXPLORATION COMPANY

Address: PO BOX 416

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Rector, Brian		brector1983@gmail.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
, Argali Exploration Company	970-629-1906	argaliexplorationcompany@gmail.com	
Rector, Jeff		jbrduco@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230411	WELL	PR	07/01/2019	GW	103-08074	FEDERAL 1-32	PR

General Comment:**COGCC Inspection Report Summary.**

On 3-6-2020 at approximately 7:55, inspector Rick Moran, conducted a follow up inspection at Argali Exploration Company well Federal 1-32 in Rio Blanco county of FIR documents:

- 1) 679703128, dated 2-27-2019.
- 2) 679704675, dated 7-1-2019.
- 3) 679705170, dated 8-20-2019.
- 4) 679706052, dated 11-12-2019.
- 5) 679706677, dated 12-23-2019.

The following compliance issues were observed as uncompleted:

- 1) Unused tanks. Photo 2 & 4. Complete by 5-30-2019.
- 2) Weeds in pit. Photo 3 & 5. Complete by 3-12-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400355.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Two unused ~10 bbl tanks on location. Unclear if tanks are intended to replace pits. Tanks have holes.		
Corrective Action:	Comply with Rule 603.f.	Date:	05/30/2020
Type	WEEDS		
Comment:	Weeds & vegetation in pits.		
Corrective Action:	Comply with Rule 603.f.	Date:	03/05/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 230411	Type: WELL	API Number: 103-08074	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: ☐Pit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Meter building pit.Corrective Date: **Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: ☐Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: Type: BlowdownLined: ☐Pit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Well head pit.Corrective Date: **Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date:

Inspector Name: Moran, Rick

Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective		
		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402335664	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088393
700400356	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088380