

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2020

Submitted Date:

03/10/2020

Document Number:

699800716

FIELD INSPECTION FORM

Loc ID: 334551 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285288	WELL	PR	03/01/2017	GW	077-09088	MITCHELL FED. 32-12	PR
285289	WELL	PR	06/21/2006	GW	077-09086	MITCHELL 32-3	PR
285290	WELL	PR	09/01/2007	GW	077-09085	MITCHELL FED. 32-4	PR
285783	WELL	PR	03/01/2017	GW	077-09109	MITCHELL FED. 32-5	PR
285784	WELL	PR	09/01/2018	GW	077-09108	MITCHELL 32-6	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Tuesday 3/10/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, conducted an on-site inspection at LARAMIE ENERGY LLC Mitchell /32-6 Pad, Location #334551 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Unused 2" piping by separators. See photo #0733 with a corrective action date of 3/25/20. Multiple holes through out tank containment liner. See photo #0734, #0735 and #0736 with a corrective action date of 3/30/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused 2" piping by separators. See photo #0733		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused piping from location.		Date: 03/25/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Livestock panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:			Date:
Equipment:			
Type:	Pig Station	# 1	corrective date
Comment:			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Adequate
Comment:	Multiple holes through out tank containment liner. See photo #0734, #0735 and #0736			
Corrective Action:	Secondary containment devices shall be sufficiently impervious to contain any spilled or released material. Repair all holes in tank containment liner.			Date: 03/30/2020

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	285288	Type:	WELL	API Number:	077-09088	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	285289	Type:	WELL	API Number:	077-09086	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	285290	Type:	WELL	API Number:	077-09085	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	285783	Type:	WELL	API Number:	077-09109	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	285784	Type:	WELL	API Number:	077-09108	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Ditches						
		Compaction				
Gravel						
Compaction						
Berms						
		Gravel				
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402339195	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092118
699800717	Photos for Insp. #699800716	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092101